

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES

VC/C:

Post Office Box 2063 Harrisburg, Pennsylvania 17120 ORIGINAL (Red)

Bureau of Waste Management

Preliminary Assessment

FOR

TEXAS EASTERN GAS PIPELINE ROCKWOOD STATION 22 PA #2165

> Black Township Somerset County Pennsylvania





COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL RESOURCES

Bureau of Solid Waste Management R. D. #3, Wilmore Road P. O. Box 625 Ebensburg, PA 15931-0625 June 16, 1987

814-472-6330

NARRATIVE SUMMARY - William Shawley

Texas Eastern Gas Pipeline Company Rockwood Compressor Station Somerset Co., Black Twp.

This site is an inactive compressor station which is now used only as a head-quarters for a Texas Eastern guaging crew. The site was formerly used as a pump station for crude oil and other petroleum products and had a 65,000 barrel storage tank which has been dismantled and removed. About 20 years ago, Texas Eastern bought the pipeline and the pump station and has been using it solely for natural gas. There are no compressors at the site at present. Two pipe lines cross the site; (1 20" and 24").

Site maps included with the Weston Reports indicate a disposal pit, dismantled storage tank, dismantled slop tank, a crushed PCB drum area, and underground concrete sump tanks.

A more extensive site history is located in the Weston Report and in the PA DER Bureau of Waste Management files in Pittsburgh. These files and maps indicate that at some time waste was disposed of in pits located at this site and that a potential exists for surface water, ground water and soils contamination from PCB's and possibly volatile organic and semivolatile organic compounds. Several water samples taken by myself and Eric Manges, Hydrogeologist, Pittsburgh Regional Office of Bureau of Waste Management did not indicate any contamination.

Texas Eastern has been ordered by PA DER to supply information and records if available and to do further sampling at this site. Due to the fact that this site is not an active compressor station, the contamination potential is probably lower than at other Texas Eastern sites but there is still a need for additional testing information.

I recommend that a more complete site history should be obtained from Texas Eastern concerning the disposal practices at this site and that additional sampling and investigation should be done at the locations of the PCB drum area, disposal pit, sumps, and dismantled tank.

;:

I IDENTIFICATION					
POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 1 - SITE INFORMATION AND ASSESSMENT					
PARI 1 - SITE INFORMATION AND ASSESSMENT					
II. SITE NAME AND LOCATION					
ROCKWOOD COMPRESSOR S		T-	512	ecific location identifier 1 Mile South a	of Bando
Black Twip - Rockwood R.D. 1 PA 15557 Somerset					CODE DIST
39 56'18.0" 079'09	1TUDE 6.12.0"				
10 DIRECTIONS TO SITE ISLATING FOR NEW PROCESSION IN LR 55044 (Mud Pike) proceed proceed south on T-512 abo	east by mile	of inite to	LR 5504 ON LR 55 He site.	3 (water level 1 5044. Tuan Ary	road) and ght and
III. RESPONSIBLE PARTIES					
Texus Eastern Gas Pipeline (· o.	f	O. Box	2521	
03 CITY		04 STATE	OS ZIP CODE	OB TELEPHONE NUMBER	ſ
Houston		TX	77252	(713) 754-3580	
07 OPERATOR (if xnown and different from owner)		OS STREET	(Business, making resk	sential)	
09 CITY		10 STATE	11 ZIP CODE	12 TELEPHONE NUMBER	-
13 TYPE OF OWNERSHIP (Check one)					
© A. PRIVATE ☐ B. FEDERAL: ☐ C. STATE ☐ D.COUNTY ☐ E. MUNICIPAL ☐ F. OTHER: ☐ G. UNKNOWN				INICIPAL	
14 OWNER/OPERATOR NOTIFICATION ON FILE (Check as that abovy) A. RCRA 3001 DATE RECEIVED: / / S. B. UNCONTROLLED WASTE SITE (CERCL4: 23 c) DATE RECEIVED: / / MONTH DAY YEAR C. NONE					
IV. CHARACTERIZATION OF POTENTIAL HAZARD					
BY ICHOES AN INTERIORY X YES DATE 3, 2, 87 NO NO NOTH DAY YEAR BY ICHOES AN INTER-SOURCE BY ICHOES					
02 SITE STATUS (Check one)	03 YEARS OF OPER				
□ A. ACTIVE 및 B. INACTIVE □ C. UNKNOWN SEGINNING YEAR ENDING YEAR					
Pipeline condensate, interface materials, degreasing solvents, PCBIS.					
Possible soils and/or groundwater contaminations					
V. PRIORITY ASSESSMENT					
01 PRIORITY FOR INSPECTION (Check one, if high or medium is checked, compare part 2 - Waste information and Part 3 - Description of ™azardous Canditions and incidents! □ A, HIGH □ B, MEDIUM □ C, LOW □ D NONE (Inspection required promotity) (Inspection required promotity) (Inspection required promotity)					
VI. INFORMATION AVAILABLE FROM					
01 CONTACT 02 OF IAGRES OF ORDINATION 03 TELEPHONE NUMBER					
Art Dalla Piazza	PA Dept. c	of Env.	Res., Bur.	of Waste Mgm t	17171783-7816
William Shawley	PA DER			07 TELEPHONE NUMBER (814) 472-6330	08 DATE 4 , 17, 87

ŞEF	A	POT	ENTIAL HAZAF PRELIMINARY PART 2 - WAST	ASSESSMENT	Γ	1. IDENTIFICATION OF STATE OF	
II. WASTE ST	TATES, QUANTITIES, AP	O CHARACTER	STICS				
OT PHYSICAL ST C A SOLID C B POWDE C C SLUDGE L D QTHER		TONS .	if waste quantities and equipment)	XA TOXIC _ 8 CORPC _ C RACIO	DSIVE F INFEC	BLE I HIGHLY V TIOUS J EXPLOSI MABLE K REACTIV	VE /E ATIBLE
III. WASTE T	YPE			<u> </u>			
CATEGORY	SUBSTANCE	NAME	01 GROSS AMOUNT	02 UNIT OF MEASUR	E 03 COMMENTS		
SLU	SLUDGE			<u> </u>			
OLW	OILY WASTE		Unknown		- Possible	Crude & Autre	Leum Product
SOL	SOLVENTS		UnKnown		- Possible d	Crude & Petro egreasing solv	entc
PSO	PESTICIDES				7-22-13-10-14	Cyrcasiny sore	
осс	OTHER ORGANIC C	HEMICALS					
ioc	INORGANIC CHEMIC						
ACD	ACIOS						
BAS	BASES				<u> </u>		
MES	HEAVY METALS			 			
	OUS SUBSTANCES (See	Lognory for most frequen	ITY CHAR CAS NUMBERS	1			
01 CATEGORY	02 SUBSTANCE	NAME	R38MUN 2AD ED	04 STOPAGE OF	SPOSAL METHOD	05 CONCENTRATION	OS MEASURE OF CONCENTRATION
V. FEEDSTO	CKS (See Accorded for CAS Mem	ooru					
CATEGORY	01 FEEDSTO	CK NAME	02 CAS NUMBER	CATEGORY	OFFEEDST	OCK NAME	02 CAS NUMBER
FDS				FOS			
FDS				FDS			
FDS				FDS			
FDS		4	1	FDS	<u> </u>		
	S OF INFORMATION ICA	8 specific references = o	State fres Samore analysis		<u> </u>		
West	on Report (Consultant	for Texus	Eastern)	submitted	to EPA and	PA DER.
stat	e files and	sampling	informatio.	м.			

0.0771.711.11	A ZA DOOLIS WASTE SITE	I. IDENTIFE	CATION
POTENTIAL	AZARDOUS WASTE SITE NARY ASSESSMENT	OI STATE 02	SITE NUMBER
	LZARDOUS CONDITIONS AND INCID	ENTS PA	
	ZARDOGG GONDINGNG AND INGID		
II. HAZARDOUS CONDITIONS AND INCIDENTS		-	
01 & A. GROUNDWATER CONTAMINATION UN KNOWN	02 TOBSERVED (DATE	A POTENTIAL	I ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	OF MARKATIVE DESCRIPTION		
			· .
	02 T OBSERVED (DATE.) X POTENTIAL	_ ALLEGED
01 X B. SURFACE WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED. Un Kno Lun.	04 NARRATIVE DESCRIPTION	A POTENTIAL	_ ^ccedeb \
,			
•			
01 T C CONTAMINATION OF AIR	02 _ OBSERVED(DATE) T POTENTIAL	_ ALLEGED
03 POPULATION POTENTIALLY AFFECTED	04 NARRATIVE DESCRIPTION		
	•		
01 T. D. FIRE-EXPLOSIVE CONDITIONS 03 POPULATION POTENTIALLY AFFECTED:	02 T OBSERVED (DATE) _ POTENTIAL	_ ALLEGED
,	OF HARRATIVE DESCRIPTION		
			-
			•
01 T E DIRECT CONTACT	02 _ OBSERVED (DATE	POTENTIAL	ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION		
01 X F CONTAMINATION OF SOIL 03 AREA POTENTIALLY AFFECTED: UNKNOWN) X POTENTIAL	_ ALLEGED
03 AREA POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION		
•			
01 TH. WORKER EXPOSURE/INJURY	UZ _ UBSERVEU (UATE.	., -	
03 WORKERS POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION		
	• .		
01 TE POPULATION EXPOSURE/INJURY) C POTENTIAL	I ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION		
	• •		

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT		I. IDENTIFIC	
		OI STATE 02 S	SITE NUMBER
PART 3 - DESCRIPTION	N OF HAZARDOUS CONDITIONS AND INCIDEN	rs L	
IL HAZARDOUS CONDITIONS AND INCIDENTS (Con	nmu ed i		
01 C J. DAMAGE TO FLORA 04 NARRATIVE DESCRIPTION	02 TOBSERVED (DATE)	☐ POTENTIAL	_ ALLEGED
01 C. K. DAMAGE TO FAUNA 04 NARRATIVE DESCRIPTION (MCNde namera) of 30 ec/est	02 C OBSERVEO (DATE)	C POTENTIAL	C ALLEGED
01 T. L. CONTAMINATION OF FOOD CHAIN 04 NARRATIVE DESCRIPTION	02 TOBSERVED (DATE:)	C POTENTIAL	C ALLEGED
01 . M. UNSTABLE CONTAINMENT OF WASTES (Solds unpolifystending squids/leasing drums) 03 POPULATION POTENTIALLY AFFECTED:	02 TOBSERVED (DATE) 04 NARRATIVE DESCRIPTION	☐ POTENTIAL	□ ALLEGED
01 C N. DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION	02 TOBSERVED (DATE)	C POTENTIAL	□ ALLEGED -
01 TO. CONTAMINATION OF SEWERS, STORM DRAINS 04 NARRATIVE DESCRIPTION	S. WWTPs 02 TOBSERVED (DATE)	I POTENTIAL	C ALLEGED
01 T P ILLEGAL/UNAUTHORIZED DUMPING 04 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE)	_ POTENTIAL	I ALLEGED
05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL	OR ALLEGED HAZARDS		
III. TOTAL POPULATION POTENTIALLY AFFECTED	: less than 100		
IV. COMMENTS			
Some additional soils and determine if past practices	groundwater sampling needs and operations at this site	to be done have cause	oda problem.
V. SOURCES OF INFORMATION (Cité specific references »	g state files, sample analysis, reports)		
State files, State sample Weston report	analy ses,		
Weston report	•		

FIELD TRIP SUMMARY REPORT

This summary should be prepared in conjunction with the Preliminary Assessment, EPA Form 2070-12.

EPA Case Number _____ Site Name Rockwood Compressor Station

Site Description This site was formerly used as a pump station for crude oil and petroleum products. The pipeline was bought by Texas Eastern of least 20 years ago and now is used only as a headquarters for a Texas Eastern metering crew. Buildings on site are circa 1940's. The site lies on a gentle slope and is surrounded by a 6' cyclone fence. The site is surrounded by farm fields. There is a level area outside the fence and upslope where a 65,000 Barrel storage tank was located. This tank has born dismonthed.

Area of site (acres)

~ 8 acres

Hazardous portion, if not entire site

30' diameter disposal pit - Possibly other areas.

escription of processes/operations which took place at the site

The site has a 24" line and a 20" line passing through it which were used for pumping crude and petroleum products. The lines are now used only for natural gas and no pumping or compression operations now exist on site. The Weston site maps indicate a disposal pit, a dismantled storage tank, a dismantled slep tank a crushed PCB drum area and storage buildings. Some buildings also have been dismantled.

Waste handling/disposal practices

A 30' diameter disposal pit located in the extreme south eastern corner of the site has been filled in and is now grown over with vegetation. PCB drums were apparently crushed on site. Without talking to employees who worked at this site in the past it is difficult to determine past practices.

site topography and runoff drainage pathways. The surface of the site slopes from west to East. A spring seep is located just above the fenced area and below the former location of the large storage tank. This drainage crosses the site from NW to SE and enters a road side ditch at the SE corner of the site.

Surface or subsurface drainage areas (leachate) noted?

The eastern end of the site is fairly swampy and water seeps into the drainage ditch and into the field on the southeastern corner of the site.

Odors/stains noted?

No

Stressed vegetation noted? N_{O}

Location and description of streams or receiving waters adjacent to site. Include flow direction and observations. Note location on attached map.

All surface water from the site enters a road ditch/stream which flows southeast along Township road T-512 about 13 mile. This stream enters an unnamed tributary which flows southwest about 1 mile and then enters Wilson Creek which flows West about 2 miles and enters Coxes Creek.

Monitoring wells on site or in vicinity. Note location on attached map.

I on site well is now on site which was formerly used for drinking water.
Other monitoring wells are planned for Phase II monitoring in the April 1,87 consent order and Agreement.

Additional comments--Further description of site

Name and Title	Affiliation	Phone
nrold Grimes - Station Super	visor - Texas Eastern	(814) 886-1391
	6. r	

INSPECTION INFORMATION	Eric Manges - Hydrogeologist
Name and title of inspector(s)	Bill Shawley - Solid Waste Specialist
Agency PA DER Bur of Waste	Mgint Phone number $\frac{6111 - 814 - 472 - 8338}{12 - 645 - 7100}$
Date Mar 2, 1987	Time on site 4.0 This hours
Weather conditions: 30° Win	dy - 3 inches of new snow

ATTACHMENTS

- o Topographic map identifying site location. Include name of quadrangle map.
- o Site sketch map showing location of monitoring wells, domestic wells, municipal water supplies, and areas of concern (lagoons, leachate seeps, drums, etc.)
- o Any available sampling results or state monitoring data with map showing sample locations.

::

SUBJECT: Texas Eastern Gas Pipeline Company

Rockwood Compressor Station

PCB and VOC Contamination/Preliminary Investigation

Black Township, Somerset County

TO: Terry R. Fabian

Regional Environmental Protection

Director

Southwestern Regional Office

FROM:

Eric T. Manges ETM

Hydrogeologist

Bureau of Waste Management Southwestern Regional Office

Introduction

The initial hydrogeologic investigation has been conducted as a result of information received by this Department which indicates that the Texas Eastern Gas Pipeline Company disposed of PCB contamined oils and condensate at their compressor stations. The PCB contaminated oils were apparently disposed in unlined pits on the compressor station properties.

There are two Texas Eastern pumping facilities within 1.7 miles of each other on the same pipeline in the Rockwood area.

The first station to be investigated was not the main Rockwood Compressor Station which is intended to be the focus of this preliminary investigation. This first station, which is located in Milford Township, 1.7 miles east of the main compressor station, shall be referred to in this report as the Rockwood Guaging Station. The initial samples taken at this site shall be described in the sampling section of this report, but detailed information on this site shall not be presented at this time. If the sampling indicates a contamination problem at the site, further investigation shall be initiated.

Upon receipt of additional, more precise information from Texas Eastern, the main compressor station was located and a preliminary sampling investigation was initiated. To avoid confusion, the main compressor station shall be referred to in this report and on laboratory analysis forms as the Rockwood/Murdock Compressor Station. This is the station at which Texas Eastern has admitted to disposing of PCB contaminated fluids.

The Rockwood/Murdock Compressor Station is located in southern Somerset County, 1.5 miles south of the village of Murdock. This site is situated at latitude 39°56'18" North and longitude 79°06'12" West on the Murdock, Pa. 7.5' U.S.G.S. Quadrangle Map.

Site Description

The Rockwood/Murdock Compressor Station is located on the northwestern flank of the Negro Mountain in the Allegheny Moutain section of the Appalacian plateau province. This station is located on the top of a small ridge at an elevation of 2,000 feet. The groundwater discharges and surface waters from the site drain to the southeast into a small tributary of Wilson Creek. Wilson Creek enters into Coxes Creek approximately two miles west of the tributary (see attached topographic map).

The site is surrounded by a 6-foot high cyclone fence which has deteriorated in several places and allows for easy access to the site.

Texas Eastern employees at the site have indicated that the facility has not been used as a compressor station for many years and that the lines currently only pass through the property. The buildings on the site appear to be circa 1940's and the site in general appeared to be defunct.

Disposal Pit

The station layout map (attached), supplied by Weston, indicated that the disposal pit is located in the extreme eastern corner of the facility property. A Texas Eastern employee helped to verify the location of the pit. A small stream channel conveying upslope spring water passes within 25 feet of the disposal pit. The pit has been backfilled and regraded, but no vegetation has been established on the overlying soil.

Potentially Affected Water Supplies

A spring, which originates topographically upslope and just above the fenced area, flows through the western portion of the fenced property and within 25 feet of the disposal site. This water flows into a roadside drainageway which runs along the public road in front of the facility. As the drainage ditch advances away from the site, it develops into a small stream. This drainageway/stream also collects all other drainage from the site and conveys it to the tributary of Wilson Creek. The eastern portion of the site is fairly swampy and also seeps into the drainageway.

An off-site spring enters the drainageway approximately 100 feet downstream from the on-site spring. This spring is topographically downslope from the disposal pit and is located on the property of Paul Boden.

An on-site drilled well exists next to the office and maintenance building, approximately 100 feet west and upgradient of the disposal pit.

An off-site drilled well exists just off of the northwest corner of the fenced area on the Leroy Roberts property. This well is approximately 280 feet northwest and upgradient from the disposal pit.

• :

Hydrogeology

away from

The general dip of the regional rock strata in the area is the access of the Negro Mountain Anticline which lies approximately 2.5 miles southeast of the site. The strata beneath the site is composed of interbedded layers of sandstone, shale and limestone in the Glenshaw Formation of the Conemaugh Rock Group. The characteristic jointing and fracturing in this formation will allow for good water conveyance, especially in the sandstone layers.

It would be expected that the regional groundwater flow direction will follow the general slope of the underlying rock strata which is to the southeast. In many cases, a shallow topographically-controlled water-bearing zone may exist, depending upon the depth of soil, the topographic slope, and the degree to which the uppermost rock layers have been weathered. As a result, groundwater flow directions may vary between shallow and deep water zones.

Sampling

The sampling of the Rockwood Guaging Station occurred on February 28, 1987. No disposal pit was observed at this site. The following is a list of the samples and their description (see attached station layout map for locations):

I.D. Number	Description
2518308	The state of the s
2518309	
2518310	Control of the contro
2518311	Tributary to Coxes Creek (adjacent to north edge of site)

The sampling at the Rockwood/Murdock Compressor Station occurred on March 2, 1987. The following is a list of the samples and their descriptions:

I.D. Number		<u>Description</u>
2518312		On-site well
2518313		On-site spring channel
2518314		Roberts Well
2518315	77	Boden Spring
2518316	,,	Off-site ditch/stream
2518317		On-site spring channel sediment
2518318		Off-site ditch/stream sediment

• •

All water sample points were analyzed for PCB's, VOC's and metals.

Soil samples from the pits were not obtained. The disposal pits have been backfilled and regraded since the cessation of disposal activities. It was not possible to obtain a sample at depth due to lack of equipment and time constraints.

Comments & Recommendations:

- 1. The disposal pit is located next to the fence at the eastern corner of the property. The fence has numerous breaks that allow for easy access to the site and the disposal pit. The entire fence should be completely secured.
- If contamination is observed in any of the sample analysis results, the sampling point in question should be immediately resampled for further verification.
- 3. If contamination is confirmed at any of the sampling locations, a thorough assessment of the type, location and extent of the contamination should be carried out according to the requirements set forth in 25 Pa. Code \$75.264(n). A abatement/clean-up plan should also be prepared and initiated.
- 4. Soil sampling of the disposal pits should be conducted through drilling with split spoon samplers. Samples should be obtained at one foot intervals.
- 5. If contaminants are detected in the on-site spring channel next to the disposal pit, (No. 2518313, No. 2518317), then the spring origin, just upslope (south edge) from the fenced property, should be sampled.
- 6. The on-site and off-site wells are both geologically and topographically upgradient from the disposal pit. There does not appear to be an immediate contamination threat to any public or private water supplies.

It does appear that there is a possibility of degradation of the local environment around the eastern corner of the site. The results of sediment samples taken in this area should help to ascertain whether hazardous pollutants have migrated off site.

ETM/ksw

cc:

